



FIRE SAFE TEST CERTIFICATE

Valve Type: **BALL VALVE MODEL 3PZ SIZE DN 2" FB CLASS 300**
To Drawing N° **N24900-DPL rev.0**
Date **12-mag-2021**

CERTIFICATE NUMBER: **IS-272293-01-21**

CLIENT: **PENTA S.r.l.**
ADDRESS: **VIA BOCCACCIO, 23**
25080 MOLINETTO DI MAZZANO (BS)

REPORT NUMBER: **N° 02/05/2021 N24900-DPL**

SCOPE OF REPORT: Fire Safe test carried out according to Client procedure
API SPECIFICATION 6FA Fifth Edition, May 2020
BS - UNI EN ISO 10497:2010
API STANDARD 607 Seventh Edition, June 2016

max bar: **40,7**

max °C: **874**



CERTIFICATION DATE

03/06/2021



TÜV ITALIA S.R.L.
TÜV SÜD Group

Telefono: +39 02 24130.1
Telefax: +39 02 24130.399

www.tuv.it

Direzione e Sede Amministrativa:
Via Giosué Carducci, 125 edificio 23
20099 Sesto San Giovanni (MI)
Sede legale: Via Mauro Macchi, 27 20124 Milano
Società soggetta al controllo e al coordinamento di
TÜV SÜD AG

Registro delle imprese di Milano
n. iscrizione e Cod. Fisc. 08922920155
R.E.A. 1255140 - P. IVA 02055510966
Capitale sociale : Euro 500.000 int. vers.
Coord. Bancarie: INTESA BCI - CIN J
c/c 000018978166 - ABI 03069 - CAB 32934
IBAN: IT34 J030 6932 9340 0001 8978 166



Italia

FIRE SAFE TECHNICAL REPORT

FIRE SAFE CERTIFICATE N°: IS-276165-01-21

REPORT N°: N° 02/05/2021 N24900-DPL

CLIENT: PENTA S.r.l.

ADDRESS: VIA BOCCACCIO, 23 - 25080 MOLINETTO DI MAZZANO (BS)

QUALIFIED VALVE

<u>VALVE SIZE:</u>	2"
<u>VALVE RATING CLASS:</u>	300
<u>DRAWING N°:</u>	N° N24900-DPL rev.0
<u>VALVE TYPE:</u>	BALL VALVE MODEL 3PZ SIZE DN 2" FB CLASS 300
<u>MAX bar:</u>	40,7
<u>MAX °C:</u>	874

<u>RANGE AND TYPE OF</u>	NPS: 2"; 2½"; 3"; 4" (API6D) - DN: 50; 65; 80; 100 (API6FA)
	NPS: 2" and below; 2½"; 3"; 4" DN: 50 and below; 65; 80; 100 (ISO 10497 and API607)
<u>VALVES COVERED:</u>	CLASS: 300; 600 (API6FA)
	CLASS: 300; 400; 600 - PN 40; 63; 100 (ISO 10497 and API607)

THE ABOVE MENTIONED VALVE SUCCESSFULLY PASSED THE FIRE SAFE IN ACCORDANCE TO:

API SPECIFICATION 6FA Fifth Edition, May 2020

API STANDARD 607 Seventh Edition, June 2016

BS - UNI EN ISO 10497:2010

NOTES:

LOCATION AND DATE OF TEST CARRIED OUT:

At CO.MA.IS. s.a.s. - Via Marelli, 70 - 20043 Cerro Maggiore (MI) - 28/05/2021

TÜV
INSPECTOR

